

TOWN OF BEDFORD

Facilities Masterplan 18 July 2018



Town Facilities for this study includes the following facilities and locations:

Town Hall

■ Bedford Town Hall – 70 Bedford Center Road

Municipal Offices

Bedford Town Office – 24 North Amherst Road (main building only).

Public Meeting Room

BCTV – 10 Meetinghouse Road

Public Works

- Highway Garage 19 Chubbuck Road
- Transfer Station 77 Chubbuck Road

<u>Library</u>

Town Library – 3 Meetinghouse Road

Public Safety WW OFFICE

Bedford Safety Complex – 55 Constitution Drive

Storage, Maintenance, and Services MASHUAROAD FACILITY

- Nashua Road Facility (old Highway Garage) 19 Nashua Road
- TRM Storage Building Leased space on Sunset Drive

Pools / Bath House

Bedford Pool Facility – 20 County Road

Community Center

Stevens-Buswell Building – 18 North Amherst Road




SCOPE


Develop a plan that will identify short and long term improvements which will achieve the following objectives:

- 1. Develop Space Needs Analysis
- 2. Evaluate services for feasibility of combining or co-locating
- 3. Evaluate the physical location of town facilities for highest and best use
- 4. Evaluate public safety location and plan
- 5. Evaluate safety and security needs
- 6. Evaluate potential for leased space or other options
- 7. Evaluate feasibility and provide cost analysis as well as cost benefit analysis.
- 8. Develop a phasing and implementation plan.

Evaluation at Three Scales

- PROGRAM
- FACILITY
- TOWN





FACILITY ASSESSMENTS

HIGHWAY GARAGE

Summary of work

- 1. Existing conditions information was gathered
- 2. Architectural and engineering team performed onsite assessments of each building
- 3. Team verified building dimensions
- 4. Updated existing conditions plans and massing model were created
- 5. 7 page assessment per building was created
















Review Categories


- Site issues, needs, and observations
- Exposed building structure
- Exterior building envelope 3.
- Life Safety
- Interior finish conditions
- 6. Electrical systems
- Lighting systems
- Mechanical systems
- Plumbing systems 9.





AVERAGE FACILITY RATING












Overall Condition Rating Fair-Good





Observations and Deficiencies Summary

Site access is very good for a potential fire substation although the S. River Rd intersection should be signalized

Utilities include public water and sewer

Recent upgrades include fit up work for the lease use and significant electrical improvements


Pre-manufactured steel structure appears to be in very good condition

Exterior siding and storefront are in good condition

Most/all interior finishes would need to be replaced for a major renovation

It is unclear if the existing building is truly suitable for use as a fire substation

Building is not sprinklered and fire alarm strobes need to be added for better coverage











Site Size 2.96 Acres

Year Constructed 1900 / 1962

> Office Use

Building GSF 6,909 (5,088 / 1,820)

Number of Floors 1 (1 + Mezzanine)

Construction type Wood / CMU & Steel

Overall Average Rating 1.96 / 3.39

(Scale of 0-5)

Overall Condition Rating Poor-Fair / Good - Very Good

0	1	2	3	4	5
1962	Poor	Fair	Good	Very Good	Brand New



Observations and Deficiencies Summary

Building is located in the center of the historic village

Limited parking is insufficient for accommodating public meetings and is shared with Town Hall

Recent upgrades include interior finishes in the BCTV building

Annex structure is bowed and requires additional reinforcing

Exterior

Most interior finishes are in need of repair or replacement

Building is not sprinklered and fire alarm strobes need to be added for better coverage







10 Meetinghouse Rd Address

Site Size 2.96 Acres

Year Constructed 1900 / 1962

> Office Use

Building GSF 6,909 (5,088 / 1,820)

Number of Floors 1 (1 + Mezzanine)

Construction type Wood / CMU & Steel

Overall Average Rating 1.96 / 3.39

(Scale of 0-5)

Overall Condition Rating Poor-Fair / Good - Very Good

0	1	2	3	4	5
1000					7



Observations and Deficiencies Summary

Building is located in the center of the historic village

Limited parking is insufficient for accommodating public meetings and is shared with Town Hall

Recent upgrades include steel reinforcement to the Annex building

Wood structure is bowed and requires additional reinforcing

Exterior shows minor signs of rot and windows should be re-glazed or replaced; siding and roof are in good condition

Interior is not finished in most areas

Interior accessibility improvements are needed for ADA compliance including an stair and possible lift if second floor becomes occupied

Building is not sprinklered and fire alarm system needs to be improved











Year Constructed 1990

Use Office/Storage

Building GSF 13,828

Number of Floors 1 (1 + Mezzanine)

Construction type Pre-engineered Steel/Wood

Overall Average Rating 2.73

(Scale of 0-5)

Overall Condition Rating Fair - Good



0	1	2	3	4	5
100					
	Poor	Fair	Good	Very Good	Brand New



Observations and Deficiencies Summary

Site access and circulation is good for fleet

Improve visitor and staff parking / circulation

Recent upgrades include roof repairs and new carbon monoxide exhaust system

Pre-manufactured steel structure appears to be in good condition

Exterior siding, doors, and canopies are generally in need of repair

Most interior finishes are in need of repair or replacement

Interior accessibility improvements are needed for ADA compliance including an enclosed second stair and elevator or lift

Building is not sprinklered and fire alarm strobes need to be added for better coverage





SECOND FLOOR PLAN







Year Constructed 1990

Use Office/Storage

Building GSF 13,828

Number of Floors 1 (1 + Mezzanine)

Construction type Pre-engineered Steel/Wood

Overall Average Rating 2.73

(Scale of 0-5)

Overall Condition Rating Fair - Good

0	1	2	3	4	5
///					
	Poor	Fair	Good	Very Good	Srand New



Observations and Deficiencies Summary

Site access and circulation is tight, book return creates a choke point at entry

Proposed parking expansion will be an improvement

Recent upgrades include geothermal system

Visible structure appears to be in good condition

Exterior veneer, siding, doors, and canopies are well maintained and are generally in good condition

Most interior finishes are in fair to good condition but are heavily used and require replacement in some areas

Interior accessibility is good although communicating stair is narrow

Drainage from lower level plumbing to septic is a problem but most systems are in good condition

Building is fully sprinklered and fire alarm system appears to meet requirements











Observations and Deficiencies Summary

Site access is convenient to service and access central Bedford facilities but is remote from the Highway Garage

Awkward adjacency to parking for fields

Recent upgrades include site improvements

Wood structure appears to be in fair condition and cracking was observed in several locations of the CMU exterior walls

Exterior siding, doors, and canopies are generally in need of repair

Most interior finishes have not been maintained due to the unoccupied storage use of the facility

There is a portable toilet outside the building, there is no working indoor toilet.

Building is not sprinklered and does not have a fire alarm system








Address 20 County Rd Site Size 29.57 Acres Year Constructed 2003 Use Office/Storage Building GSF 3,000 Number of Floors 1 Construction Type CMU Overall Average Rating (Scale of 0-5) Overall Condition Rating Good - Very Good

Brand New



Observations and Deficiencies Summary

Site access and parking are adequate

Recent upgrades include improvements to the mechanical system which is in good condition and LED lighting in the parking lot

Visible structure appeared to be in fair to good condition and minor cracks were observed in the CMU exterior walls

Exterior siding, doors, and trim is in need of repair and/or repainting

Interior finishes are in good condition but flooring is very worn and service areas are mostly unfinished

Interior accessibility is good but there are missing ADA compliance items in a few locations

Building is not sprinklered and fire alarm system appears to be adequate









Address 55 Constitution Dr

Site Size 2.31 Acres

Year Constructed 1982/1994

Use Office/Storage

Building GSF 34,972

Number of Floors 2


Construction type Steel Frame w/ Brick

Veneer/CMU

Overall Average Rating 2.65

(Scale of 0-5)

Overall Condition Rating Fair-Good



Observations and Deficiencies Summary

Site access and congested circulation are not suited for a public safety building

Secure separation of visitor and fleet vehicles is needed

Recent upgrades include roof repairs, electrical service entrance, and LED lighting

Structural steel appears to be in good condition but some corrosion was observed in the apparatus bay









Address 55 Constitution Dr

Site Size 2.31 Acres

Year Constructed 1982/1994

Use Office/Storage

Building GSF 34,972

Number of Floors 2

Construction type Steel Frame w/ Brick

Veneer/CMU

Overall Average Rating 2.65

(Scale of 0-5)

Overall Condition Rating Fair-Good

1	1	2	2	,	_
,			3		
	Poor	Fair	Good		New F
				ery	ranc

Observations and Deficiencies Summary

Exterior envelope in original building is in good condition but new CMU envelope does not provide appropriate thermal and moisture barriers

Most interior finishes are typically in need of repair or replacement

Interior accessibility improvements are needed for ADA compliance including improved stair, elevator, and door approach clearances

Building is sprinklered but fire alarm system requires improvement

Improvements needed for HVAC throughout including HEPA filtration in police area and improved ventilation throughout building

Electrical and communications systems are not secured or properly separated and should be improved







Address 18 North A

Site Size 1.20 Acres

Year Constructed 1921 / 193

Use Office

Building GSF 7,692

Number of Floors 2 (1+B)

Construction type Wood

Overall Average Rating 1.42

(Scale of 0-5)

Overall Condition Rating N/A



Observations and Deficiencies Summary

Site access and circulation is good

Unable to determine parking adequacy due to undefined building use

Building is under current renovation

Wood structure was partially exposed and appears to be in good condition

Exterior siding is generally in good condition

Interior finishes were not complete at time of assessment

Major building systems were not complete at time of assessment

Life safety systems were not complete at time of assessment











Site Size 2.96 Acres

Year Constructed 1910

Jse Assembly

Building GSF 13,271


Number of Floors 2 + Mezzanine

Construction type Wood

Overall Average Rating 2.43

(Scale of 0-5)

Overall Condition Rating Fair-Good





Observations and Deficiencies Summary

Building is on the National Register of Historic Places

Limited parking is insufficient for accommodating public events and is shared with BCTV


Visible structure was limited to basement lally columns supporting the first floor framing


Exterior elements are in good condition for their age

Most interior finishes are in fair condition but there are many areas in need of repair or replacement from wear or water damage

Interior accessibility improvements throughout are needed for ADA compliance

Building is sprinklered and fire alarm strobes and emergency lighting need to be added for better coverage









Address 24 North Amherst Rd Site Size 5.30 Acres Year Constructed 1987 Use Office Building GSF 10,368 Number of Floors 2 Construction Type Steel & Wood Overall Average Rating (Scale of 0-5) Overall Condition Rating Fair-to-Good



Observations and Deficiencies Summary

Site access and circulation is good

Upper level parking is shared with Stevens-Buswell building

Recent upgrades include renovations of areas such as the Planning Department

Wood structure was not visible but construction was reported not to meet commercial standards

Exterior siding, doors, and canopies are generally in fair to good condition

Most interior finishes have been updated recently and issues are mainly limited to worn flooring

Interior accessibility improvements are needed for ADA compliance including a second stair, improved approach clearances at doors, and fire strobe mounting heights

Building is not sprinklered and fire alarm system appears to meet code requirements









Year Constructed 1995

Use Office/Storage

Building GSF 2,676

Number of Floors 1

Construction type Pre-engineered Steel/Wood

Overall Average Rating 1.70 (Scale of 0-5)

Overall Condition Rating Poor







Observations and Deficiencies Summary

Site access and circulation is constrained and congested

Safety issues between visitors and large dumpster transport trucks occur during high use times, weekly


No issues in the pre-manufactured steel structure were observed

Exterior metal siding and doors are generally in need of repair


Most interior finishes, which are limited, are in need of repair or replacement

Interior accessibility improvements are needed for ADA compliance for staff and visitors

Building is not sprinklered and fire alarm systems appear to meet code requirements









Observations and Deficiencies Summary

Site access and circulation is constrained and congested

Safety issues between visitors and large dumpster transport trucks occur during high use times, weekly


No issues in the steel structure were observed

Exterior metal siding and doors are generally in need of repair


There are no finished interior spaces

Building is not sprinklered and fire alarm systems appear to meet code requirements





ADDITIONAL SITE ASSESSMENTS



Key Noted Site Plan: See 'Site Issues, Needs, and Observations'

Site Plan Legend

- A. Route 101
- B. Constitution Drive
- C. 2 Constitution Drive
- D. 55 Constitution Drive
- E. 47 Constitution Drive

Zoning Provisions

Zone: "OF" Office


Permitted Uses: Offices, Research and Development facilities.

Observations Summary

Reviewed for consideration with 55 Constitution Drive

Parcel could increase site size to relieve parking, access, and security concerns





Key Noted Site Plan: See 'Site Issues, Needs, and Observations'

Site Plan Legend

A. Route 101

B. Constitution Drive

C. 2 Constitution Drive

D. 55 Constitution Drive

E. 47 Constitution Drive

Zoning Provisions


Zone: "OF" Office

Permitted Uses: Offices, Research and Development facilities.

Observations Summary

Reviewed for consideration with 55 Constitution Drive

Parcel could increase site size to relieve parking, access, and security concerns





Key Noted Site Plan: See 'Site Issues, Needs, and Observations'

Site Plan Legend A. Constitution Drive

15 Constitution Drive

Zoning Provisions

Zone: "OF" Office

Permitted Uses: Offices, Research and Development facilities.

Observations Summary

Reviewed for consideration as a single municipal facility to replace Town Office, Police Department, and potentially BCTV and Library

Police Department is incompatible as an integrated part of a combined facility and existing building is much larger than the Town needs





Key Noted Site Plan: See 'Site Issues, Needs, and Observations'

Zoning Provisions

Zone: "PZ" Performance Zoning District


Permitted Uses: Various commercial uses and industrial uses.

Observations Summary

Reviewed for consideration as an alternative location for fire substation or combined substation and police department

Location is very remote to provide service needed from the Police Department





SPACE NEEDS ASSESSMENTS


Summary of work


- 1. Existing conditions information was gathered via questionnaires
 - Current area used per department or division
 - Current needs required
 - What works well and does not work in current space
 - Required adjacencies to other departments
 - Parking needs
 - Review of underutilized and over utilized spaces
- 2. Team performed onsite interviews with each department head
- Updated existing conditions plans were versified and coded per program use
- 4. Space Needs assessment was created documenting
 - Current area used
 - Current area needed
 - Space utilization
 - Future space needs












PERCENTAGE OF SPACE NEED PROVIDED BY EXISTING FACILITIES BY DEPARTMENT

100% = CURRENT SPACE NEED



PERCENTAGE OF SPACE NEED PROVIDED BY EXISTING FACILITIES BY GROUP

gross building area: Area of entire building including exterior walls

net usable area assigned to Interior area of each room per department. Interior walls are departments: excluded

shared space: Includes usable space such as conference rooms, storage rooms, etc. that are not assigned to a department

circulation (corridors, stairs, elevators): This includes the area of entry lobbies, corridors, elevators and stairs

building services: Includes the areas allocated to mechanical, utility, restrooms

walls and partitions: Includes the total area of all exterior walls and partitions throughout the building

SPACE NEEDS

		Exist	2017	2022	2027	2037		Delta
	Description	Current Area	Net Area Required (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Total Net Area Required (sf)	Between Exist and Required Area (sf)
A1.	Assessor	969	1,585	140		•	1,725	(756)
A2,	Assessor at BCTV Annex Total Assessor	56 1,025	140 1,725	140	(*)	-	140 1,865	(84) (840)
В.	BCTV	5,088	5,992	(m)	(*)		5,992	(904)
C1.	Building Dept at Safety	696	2,470	90	-		2,559	(1,863)
C2.	Building Dept at BCTV Annex	336	420	-			420	(84)
	Total Building Dept	1,032	2,890	90	8	(*)	2,979	(1,947)
D.	Town Clerk	519	637		S		637	(118)
E1.	DPW - Administrative Areas	1,749	3,373	734	-		4,106	(2,357)
E2.	DPW - Town Office Shed	384	*	-	-			384
E3.	DPW - BCTV Annex	1,160		-	-		*	1,160
E4.	DPW - Highway Garage Areas	13,828	41,870	*	-		41,870	(28,042)
E5.	DPW - Nashua Road Vehicle Storag	3,736	5,777	5	2		5,777	(2,041)
E6.	DPW - Transfer Station and Recycle	2,678	2,993	€.	-	· **	2,993	(315)
E7.	DPW - Recycle Center	1,425	2,200	*	-		2,200	(775)
	Total DPW	23,535	54,013	734	(##)	() * ()	56,947	(33,412)
F1.	Finance	2,462	3,324	179	0	0	3,503	(1,041)
F2.	Finance at BCTV	151	840	0	0	0	840	(689)
	Total Finance	2,613	4,164	179	0	0	4,343	(1,730)
G1.	Fire Department	18,670	21,823	840	0	0	22,663	(3,993)
G2.	Fire Department Sub Station	0	11,726	0	0	0	11,726	(11,726)
	Total Fire Department	18,670	33,549	840	-		34,389	(15,719)
н.	IT Manager	548	711	168	0	0	879	(331)
ı.	Library	20,400	29,289	0	0	0	29,289	(8,889)
J.	Planning	2,267	2,657	308	0	0	2,965	(698)
K1.	Police - Administration	1,386	2,335	308	0	0	2,643	(1,257)
K2.	Police - Communications	1,053	2,170	252	0	0	2,422	(1,369)
К3.	Police - Records	180	767	0	0	0	767	(587)
K4.	Police - Patrol	4,257	5,510	560	0	0	6,070	(1,813)
K5.	Police - Training	1,173	3,892	0	0	0	3,892	(2,719)
K6.	Police - Detectives	1,365	2,310	252	0	0	2,562	(1,197)

Gross Program Summary

		Exist	2017	2022	2027	2037		Delta
	Description	Current Area	Current Area Required (sf)		Anticipated Future Area (sf)	Anticipated Future Area (sf)	Total Net Area Required (sf)	Between Exist and Required Area (sf)
K7.	Police - Property & Evidence	684	2,296	252	196	112	2,856	(2,172)
K8.	Police - General Shared Space	1,341	3,640	350	0	0	3,990	(2,649)
	Total Police	11,439	22,921	1,974	196	112	25,203	(13,764)
L1.	Recreation Office	309	420	0	0	0	420	(111)
L2.	Recreation - Town Hall	13,271	13,271	0	0	0	13,271	
L3.	Recreation - Pool Facility	3,000	3,000	0	0	0	3,000	*
	Total Recreation	16,580	16,691	0	0	0	16,691	(111)
M.	Supervisor of the Checklist	197	823	0	0	0	823	(626)
N1.	Town Manager	1,405	1,456	350	0	0	1,806	(401)
N2.	Town Manager at BCTV Annex	151	350	0	0	0	350	(199)
	Total Town Manager	1,556	1,806	350	0	0	2,156	(600)
101	TAL AREA	105,469	177,869	4,782	196	112	185,159	(79,690)


S
Ш
Ш
Щ
O
4
S

Ĩ		Exist	2017	2022	2027	2037	2000000	Delta Between
	Description	Current Area	Net Area Required (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Total Net Area Required (sf)	Exist and Required Area (sf)
A1.	Assessor	551	1,132	100	0	0	1,232	(681
A2.	Assessor at BCTV Annex Total Assessor	42 593	100 1,232	0 100	0	0	100 1,332	(58 (739
В.	BCTV	3,626	4,280	0	0	0	4,280	(654
C1.	Building Dept at Safety	506	1,764	64	0	0	1,828	(1,322
C2.	Building Dept at BCTV Annex	255	300	0	0	0	300	(45
	Total Building Dept	761	2,064	64	0	0	2,128	(1,367
D.	Town Clerk	312	455	0	0	0	455	(143
E1.	DPW - Administrative Areas	993	2,409	524	0	0	2,933	(1,940
E2.	DPW - Town Office Shed	354	0	0	0	0	2	354
E3.	DPW - BCTV Annex	887	0	0	0	0		887
E4.	DPW - Highway Garage Areas	11,420	34,892	0	0	0	34,892	(23,472
E5.	DPW - Nashua Road Vehicle Stc	3,440	5,252	0	0	0	5,252	(1,812
E6.	DPW - Transfer Station and Rec	2,457	2,721	0	0	0	2,721	(264
E7.	DPW - Recycle Center	1,372	2,000	0	0	0	2,000	(628
	Total DPW	19,551	45,274	524	0	0	47,798	(28,247
F1.	Finance	1,376	2,374	128	0	0	2,502	(1,126
F2.	Finance at BCTV	114	600	0	0	0	600	(486
	Total Finance	1,490	2,974	128	0	0	3,102	(1,612
G1.	Fire Department	13,589	15,588	600	0	0	16,188	(2,599
G2.	Fire Department Sub Station	0	9,381	0	0	0	9,381	(9,381
	Total Fire Department	13,589	24,969	600	0	0	25,569	(11,980
н.	IT Manager	239	508	120	0	0	628	(389
ı.	Library	13,844	20,921	0	0	0	20,921	(7,077
J.	Planning	1,321	1,898	220	0	0	2,118	(797
K1.	Police - Administration	1,009	1,668	220	0	0	1,888	(879
K2.	Police - Communications	767	1,550	180	0	0	1,730	(963
КЗ.	Police - Records	131	548	0	0	0	548	(417
K4.	Police - Patrol	3,099	3,936	400	0	0	4,336	(1,237
K5.	Police - Training	854	2,780	0	0	0	2,780	(1,926
K6.	Police - Detectives	993	1,650	180	0	0	1,830	(837


Net Program Summary

		Exist	2017	2022	2027	2037	800000	Delta Between
	Description	Current Area	Net Area Required (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Total Net Area Required (sf)	Exist and Required Area (sf)
K7.	Police - Property & Evidence	498	1,640	180	140	80	2,040	(1,542)
K8.	Police - General Shared Space Total Police	976 8,327	2,600 16,372	250 1,410	0 140	0 80	2,850 18,002	(1,874) (9,675)
L1.	Recreation Office	176	300	0	0	0	300	(124)
L2.	Recreation - Town Hall	10,464	10,464	0	0	0	10,464	2
L3.	Recreation - Pool Facility	2,143	2,143	0	0	0	2,143	
	Total Recreation	12,783	12,907	0	0	0	12,907	(124
М.	Supervisor of the Checklist	112	588	0	0	0	588	(476
N1.	Town Manager	799	1,040	250	0	0	1,290	(491
N2.	Town Manager at BCTV Annex	114	250	0	0	0	250	(136
	Total Town Manager	913	1,290	250	0	0	1,540	(627
TOT	AL AREA	77,461	135,732	3,416	140	80	141,368	(63,907

Description	Exist	2017	2022	2027	2037	15/15/4/1/10/15/5/4	Delta Between
	Current		Net Area Required (sf) Anticipated Future Area (sf)		Anticipated Future Area (sf)	Total Net Area Required (sf)	Exist and Required Area (sf)
A1. Assessor	551	1,132	100	0	0	1,232	(681)
A2. Assessor at BCTV Annex	42	100	0	0	0	100	(58)
Total Assessor	593	1,232	100	0	0	1,332	(739)








A2. BCTV Annex

	Exist	2017	2022	2027	2037	35/25/1/2005	Delta Between
Description	Current		Anticipated Future Area (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Total Net Area Required (sf)	Exist and Required Area (sf)
A1. Assessor	551	1,132	100	0	0	1,232	(681)
A2. Assessor at BCTV Annex	42	100	0	0	0	100	(58)
Total Assessor	593	1,232	100	0	0	1,332	(739)



Spaces are split across lower level

Storage space in BCTV Annex is utilized for Assessor records

Assessor cards are commonly accessed by Planning and Building Departments

Current space lacks private meeting space

Touch down space needed for future data collector position

Office spaces are located in converted basement area

A1. Town Office - Lower Level Detail Plan





Space deficiencies result from existing shared work and office areas that should be separated

Large meeting room layout and seating capacity is low due to repurposed space

Overall, most spaces work well for the BCTV need

Description	Exist	2017	2022	2027	2037	74/29/21/M2003	Delta Between
	Current Area Required (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Total Net Area Required (sf)	Exist and Required Area (sf)	
C1. Building Dept at Safety	506	1,764	64	0	0	1,828	(1,322)
C2. Building Dept at BCTV Annex	255	300	0	0	0	300	(45)
Total Building Dept	761	2,064	64	0	0	2,128	(1,367)





C2. BCTV Annex

Description	Exist	2017	2022	2027	2037	75/29/21/06/22	Delta Between
	Current Net Area Required (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Total Net Area Required (sf)	Exist and Required Area (sf)	
C1. Building Dept at Safety	506	1,764	64	0	0	1,828	(1,322)
C2. Building Dept at BCTV Annex	255	300	0	0	0	300	(45)
Total Building Dept	761	2,064	64	0	0	2,128	(1,367)



Staff areas are located in the Upper Level of the Public Safety Building

Storage space in BCTV Annex is utilized for records

Adjacency with Fire Chief is good but adjacency with Planning and DPW Admin would improve level of service to Town

Administration and copy areas are shared with Fire Department

Lack of layout space to review plans


C1. Safety Building-Upper Level



Space deficiencies result from an existing single shared work and office area that should be separated and/or better arranged


Adjacency to the Town Manager and Supervisor of the Checklist is important

Overall, existing space works for the Town Clerk need



D1. Town Office-Upper Level

Description	Current Area	2017 Net Area Required (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Total Net Area Required (sf)	Delta Between Exist and Required Area (sf)
E1. DPW - Administrative Areas	993	2,409	524	0	0	2,933	(1,940)
E2. DPW - Town Office Shed	354	0	0	0	0		354
E3. DPW - BCTV Annex	887	0	0	0	0	2	887
E4. DPW - Highway Garage Areas	11,420	34,892	0	0	0	34,892	(23,472)
E5. DPW - Nashua Road Vehicle Stc	3,440	5,252	0	0	0	5,252	(1,812)
E6. DPW - Transfer Station and Rec	2,457	2,721	0	0	0	2,721	(264)
E7. DPW - Recycle Center	1,372	2,000	0	0	0	2,000	(628)
Total DPW	19,551	45,274	524	0	0	47,798	(28,247)



E1. Administrative Areas-Town Office-Lower Level E2. Town Office Shed



BCTV ANNEX

ASSESSOR 42 SF

DPW 853 SF

GENERAL BUILDING

BUILDING SERVICES 34 SF


CIRCULATION 238 SF

WALLS AND PARTITIONS 169 SF

E3. BCTV Annex

	Description	Exist Current Area	2017 Net Area Required	Anticipated Future Area	2027 Anticipated Future Area	2037 Anticipated Future Area	Total Net Area Required (sf)	Delta Between Exist and Required Area
		1	(sf)	(sf)	(sf)	(sf)		(sf)
E1.	DPW - Administrative Areas	993	2,409	524	0	0	2,933	(1,940)
E2.	DPW - Town Office Shed	354	0	0	0	0	73	354
E3.	DPW - BCTV Annex	887	0	0	0	0	=	887
E4.	DPW - Highway Garage Areas	11,420	34,892	0	0	0	34,892	(23,472)
E5.	DPW - Nashua Road Vehicle Stc	3,440	5,252	0	0	0	5,252	(1,812)
E6.	DPW - Transfer Station and Rec	2,457	2,721	0	0	0	2,721	(264)
E7.	DPW - Recycle Center	1,372	2,000	0	0	0	2,000	(628)
	Total DPW	19,551	45,274	524	0	0	47,798	(28,247)








E4. Highway Garage


E4. Highway Garage

E5. Nashua Road

Description	Exist Current Area	2017 Net Area Required (sf)	Anticipated Future Area (sf)	2027 Anticipated Future Area (sf)	2037 Anticipated Future Area (sf)	Total Net Area Required (sf)	Delta Between Exist and Required Area (sf)
E1. DPW - Administrative Areas	993	2,409	524	0	0	2,933	(1,940)
E2. DPW - Town Office Shed	354	0	0	0	0	-	354
E3. DPW - BCTV Annex	887	0	0	0	0	2	887
E4. DPW - Highway Garage Areas	11,420	34,892	0	0	0	34,892	(23,472)
E5. DPW - Nashua Road Vehicle Stc	3,440	5,252	0	0	0	5,252	(1,812)
E6. DPW - Transfer Station and Rec	2,457	2,721	0	0	0	2,721	(264)
E7. DPW - Recycle Center	1,372	2,000	0	0	0	2,000	(628)
Total DPW	19,551	45,274	524	0	0	47,798	(28,247)



E6. Transfer Station



E7. Recycling Center

		Exist	2017	2022	2027	2037		Delta Between
	Description	Current Area	Net Area Required (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Total Net Area Required (sf)	Exist and Required Area (sf)
E1. D	PW - Administrative Areas	993	2,409	524	0	0	2,933	(1,940)
E2. D	PW - Town Office Shed	354	0	0	0	0	5	354
E3. D	PW - BCTV Annex	887	0	0	0	0	=	887
E4. D	PW - Highway Garage Areas	11,420	34,892	0	0	0	34,892	(23,472)
E5. D	PW - Nashua Road Vehicle Stc	3,440	5,252	0	0	0	5,252	(1,812)
E6. D	PW - Transfer Station and Rec	2,457	2,721	0	0	0	2,721	(264)
E7 . D	PW - Recycle Center	1,372	2,000	0	0	0	2,000	(628)
	Total DPW	19,551	45,274	524	0	0	47,798	(28,247)

DPW program is spread across the Town and would benefit from consolidation

Space deficiencies exist in nearly all locations, especially Administrative Areas and Highway Garage: staff and vehicle space needs

Benefit from adjacency with Planning and Building Departments

Areas such as Shed and Transfer Station house office space in substandard conditions



	Exist	2017	2022	2027	2037	75/78/21/06/22	Delta Between
Description	Current Area	Required		Anticipated Future Area (sf)	Anticipated Future Area (sf)	Total Net Area Required (sf)	Exist and Required Area (sf)
F1. Finance	1,376	2,374	128	0	0	2,502	(1,126)
F2. Finance at BCTV	114	600	0	0	0	600	(486)
Total Finance	1,490	2,974	128	0	0	3,102	(1,612)


Space deficiencies are significant for this department


Additional private offices and common work areas are needed

Adjacency with Town Manager is important

Consolidate storage within the department








F1. Town Office-Upper Level

F2. BCTV Annex

	Exist	2017	2022	2027	2037	30/28/20/00/20	Delta Between
Description	Current Area (sf)	Required	equired Future Area	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Future Area Required (sf)	Exist and Required Area (sf)
G1. Fire Department	13,589	15,588	600	0	0	16,188	(2,599)
G2. Fire Department Sub Station	0	9,381	0	0	0	9,381	(9,381)
Total Fire Department	13,589	24,969	600	0	0	25,569	(11,980)




Description	Exist	2017	2022	2027	2037	V50/29/10/00/00/00	Delta Between
	Current Requ	Net Area Required (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf) Total Net Area Required (sf)	11.00	Exist and Required Area (sf)
G1. Fire Department	13,589	15,588	600	0	0	16,188	(2,599)
G2. Fire Department Sub Station	0	9,381	0	0	0	9,381	(9,381)
Total Fire Department	13,589	24,969	600	0	0	25,569	(11,980)

Space deficiencies result from existing shared work and office areas that should be separated from Police and Building Department

Administration is separated from operations

Covered area needed for trailers and other support apparatus



G1. 4 Sunset Lane Building



MANAGER'S SECRETARY GOLST WOMEN'S BATHROOM 137 SP BATHROOM 137 SP BATHROOM 138 SF COPY MALL 150 SF COPYERROE STOR 19,50 FILING FRANCE 150 SF COPYERROE 170 MCLERK FRANCE 157 SF COPYERROE 170 MCLERK FRANCE 157 SF COPYERROE 157 SF CO

H. Town Office-Upper Level

Space Needs Summary

Limited space need based on work area and server room needs

IT is under Police Department and has overlap in the Public Safety Building

Location adjacent to several Town departments is convenient

Current location off shared work/copy room and lobby can be disruptive

BUILDING 180 SF CLERK 352 SF DPW 829 SF

DEPARTMENT LEGEND - TOWN OFFICE

664 SF

ASSESSOR

FINANCE 1,090 SF

IT MANAGER 259 SF


PLANNING 838 SF

RECREATION 147 SF

CHECK-LIST SUPERVISOR 91 SF

TOWN MANAGER 682 SF





I. Library- Lower Level

I. Library- Upper Level

Description	Current Area	Net Area Required (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Total Net Area Required (sf)	Delta Between Exist and Required Area (sf)
I. Library	13,844	20,921	0	0	0	20,921	(7,077)



Significant space need based on several areas including large meeting areas, Children's Library, administration, and Young Adult area

Current location works well but is too small

Town holds all volumes in circulation resulting in tall stacks throughout and prefers enough space to lower stack heights

Option to separate access to public rooms from library program areas is needed for better off hours use of the building

I. Library- Lower Level

U
Q

Description	Exist	2017	2022	2027	2037		Delta Between
	Current Area	Net Area Required (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Total Net Area Required (sf)	Exist and Required Area (sf)
J. Planning	1,321	1,898	220	0	0	2,118	(797)

ACTIVE PLANER PLANER ASST. ORISETOR 200 SF ACTIVE PLING TRANS, WINCOW 100 SF ACTIV

Space Needs Summary

Planning department has been reconfigured but still has space needs for current and future program

Additional separation of file storage and work areas is needed


Shared meeting spaces are needed


Adjacency with DPW Administration and Town Manager is good

DEPARTMENT LEGEND - TOWN OFFICE ASSESSOR 664 SF BUILDING 180 SF 352 SF 829 SF FINANCE 1,090 SF IT MANAGER 259 SF PLANNING 838 SF 147 SF RECREATION CHECK-LIST SUPERVISOR 91 SF TOWN MANAGER 682 SF

H. Town Office-Lower Level

Description	Current Area	2017 Net Area Required (sf)	Anticipated Future Area (sf)	2027 Anticipated Future Area (sf)	2037 Anticipated Future Area (sf)	Total Net Area Required (sf)	Delta Between Exist and Required Area (sf)
K1. Police - Administration	1,009	1,668	220	0	0	1,888	(879)
K2. Police - Communications	767	1,550	180	0	0	1,730	(963)
K3. Police - Records	131	548	0	0	0	548	(417)
K4. Police - Patrol	3,099	3,936	400	0	0	4,336	(1,237)
K5. Police - Training	854	2,780	0	0	0	2,780	(1,926)
K6. Police - Detectives	993	1,650	180	0	0	1,830	(837)
K7. Police - Property & Evidence	498	1,640	180	140	80	2,040	(1,542)
K8. Police - General Shared Space Total Police	976 8,327	2,600 16,372	250 1,410	0 140	0 80	2,850 18,002	(1,874) (9,675)





G1. Public Safety Building-Upper Level

	Exist	2017	2022	2027	2037		Delta Between
Description	Current Area	Net Area Required (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Total Net Area Required (sf)	Exist and Required Area (sf)
K1. Police - Administration	1,009	1,668	220	0	0	1,888	(879)
K2. Police - Communications	767	1,550	180	0	0	1,730	(963)
K3. Police - Records	131	548	0	0	0	548	(417)
K4. Police - Patrol	3,099	3,936	400	0	0	4,336	(1,237)
K5. Police - Training	854	2,780	0	0	0	2,780	(1,926)
K6. Police - Detectives	993	1,650	180	0	0	1,830	(837)
K7. Police - Property & Evidence	498	1,640	180	140	80	2,040	(1,542)
K8. Police - General Shared Space Total Police	976 8,327	2,600 16,372	250 1,410	0 140	0 80	2,850 18,002	(1,874) (9,675)

Space deficiencies exist in all police divisions including fleet

Shared locker areas with Fire Department is remote from other police program

Administration and detectives are separated from booking and patrol by an unsecured lobby area

Repurposing of an office building has created law enforcement spaces that do not meet or make it difficult to meet national professional standards

Lack of secure site and building areas presents a safety concern for staff throughout all divisions

	Exist	2017	2022	2027	2037	12/08/2/08/59	Delta Between
Description	Current Area	Net Area Required (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Anticipated Future Area (sf)	Total Net Area Required (sf)	Exist and Required Area (sf)
L1. Recreation Office	176	300	0	0	0	300	(124)
L2. Recreation - Town Hall	10,464	10,464	0	0	0	10,464	1000
L3. Recreation - Pool Facility	2,143	2,143	0	0	0	2,143	1997
Total Recreation	12,783	12,907	0	0	0	12,907	(124)

DEPARTMENT LEGEND - TOWN OFFICE ASSESSOR 664 SF BUILDING 180 SF CLERK 352 SF DPW 829 SF FINANCE 1,090 SF FI


L1. Town Office-Upper Level

Space Needs Summary

Recreation office and storage program is spread across Bedford

Recreation office in Town Office is not well matched to community service needs and is too small

Storage for recreation supported camp supplies and activities is in the basement of Town Hall



L2. Town Hall




L3. Pool Facility



Limited space available for work and layout areas

Voting machines are stored in Public Safety Building but could be relocated to High School

Adjacency to Town Clerk is important



H. Town Office-Upper Level

1	Exist	2017	2022	2027	2037	Total Net	Delta Between
Description	Current Area Net Area Required (sf)		Anticipated Future Area (sf)	Anticipated Future Area (sf)	Future Area Future Area		Exist and Required Area (sf)
N1. Town Manager	799	1,040	250	0	0	1,290	(491)
N2. Town Manager at BCTV Annex	114	250	0	0	0	250	(136)
Total Town Manager	913	1,290	250	0	0	1,540	(627)

Space needs result from an awkward use of existing Town Office building and mismatch of current and former types of town government


Dedicated Manager's office plus adjacent shared meeting room is needed vs existing office and meeting space in single office

Location adjacent to several Finance, Town Clerk, Assessor, and Planning is convenient



H. Town Office-Upper Level

DEPARTMENT LEGEND - TOWN OFFICE 664 SF ASSESSOR BUILDING 180 SF 352 SF CLERK 829 SF FINANCE 1.090 SF IT MANAGER 259 SF PLANNING 838 SF RECREATION 147 SF CHECK-LIST SUPERVISOR 91 SF TOWN MANAGER 682 SF




SPACE UTILIZATION ANALYSIS

EXISTING BUILDING UTILIZATION SUMMARY

		PROGRAM AREA	SHARED SPACE	EXISTING (GROSS AREA	TOTAL GROSS	UTILIZATION	
	building	exist program area (sf)	shared space allocation (sf)	circulation space allocation (sf)	building services space allocation (sf)	wall and partition space allocation (sf)	total building area (sf)	building utilization percentage
		current usable area	shared space x % usable area	circulation area x % usable area	building services x % usable area	area of walls and partitions x % usable area	program area + shared space + circulation space + building services + walls and partitions	program and shared area / total area)
Α	4 Sunset Lane Leased	7,408	2 4 3	90	æ	312	7,810	94.85%
В1	всти	3,626	(7)	866	190	406	5,088	71.27%
B2	BCTV Annex	1,378	5 5 2	238	35	169	1,820	75.71%
С	Highway Garage	11,420	**	983	156	1,269	13,828	82.59%
D	Library	11,819	10 4 11	2,801	994	4,785	20,399	57.94%
Ε	Nashua Road Facility	3,440		62	19 5 1	234	3,736	92.08%
F	Pool Facility	2,143	*	459	Œ	398	3,000	71.43%

EXISTING BUILDING UTILIZATION SUMMARY

		PROGRAM AREA	SHARED SPACE	EXISTING (GROSS ARE	TOTAL GROSS	UTILIZATION	
	building	exist program area (sf)	shared space allocation (sf)	circulation space allocation (sf)	building services space allocation (sf)	wall and partition space allocation (sf)	total building area (sf)	building utilization percentage
		current usable area	shared space x % usable area	circulation area x % usable area	building services x % usable area	area of walls and partitions x % usable area	program area + shared space + circulation space + building services + walls and partitions	program and shared area / total area)
G	Public Safety Complex	23,423	2,030	4,660	739	4,117	34,972	72.78%
Н	Stevens Buswell	4,354	3.50	1,568	401	924	7,247	60.08%
I	Town Hall	10,464	*	1,045	385	1,377	13,271	78.85%
J1	Town Office	5,059	832	2,426	838	1,212	10,368	56.82%
J2	Shed at Town Office	354		ē	10	30	384	92.19%
K1	Transfer Station	2,457	-		47	174	2,678	91.75%
K2	Recycle Center	1,372		9	æ	53	1,425	96.28%
	total	88,717	2,862	15,198	3,785	15,460	126,026	72.67%



QUESTIONS